

PL62006 High Efficiency, Synchronous bi-directional Buck-Boost Charger

1 Features

- Charging management, including trickle charging, CC charging, CV charging and charging termination functions
- Wide VBUS and VBAT voltage operation range up to 32V
- Support up to 4 ports (C1 port, C2 port, B port, A port) plug-in and plug-out detection
- Support over current, over voltage protection for each port.
- 1 Cell to 6 Cells battery charge management
- Support both 4.2V and 3.5V battery charging
- Programmable switching frequency 150Khz and 300Khz
- 12-bit DAC converter to guarantee programmable current limit with10mA/step
- 12-bit DAC converter to guarantee programmable output voltage with 5mV/step
- Programmable cable drop compensation
- Integrate N-Gate drivers for up to four USB ports
- Battery voltage, BUS voltage and all ports voltage sensing on VMONP pin
- Battery current, BUS current and all ports current sensing on VMONP pin
- Comprehensive protection features in on-chip buck-boost controller
- Supports pass-through operation when VBUS is close to VBAT
- I²C interface is available to communicate with MCU
- On-chip LDO to provide power for MCU
- QFN5X5-40 package

2 Applications

- Power Bank
- Battery packs
- Li-ion Battery Charger
- Portable equipments
- General fast Charging
- Smart USB Sockets

3 Description

PL62006 is a high efficiency, synchronous bi-directional buck-boost charger. It is a comprehensive and flexible buck-boost charger platform designed for most of fast charging applications with type-C port and PD protocol. It can be programmed to buck charging, boost charging or buck-boost charging. PL62006 provides I²C interface to communicate with MCU, provides high voltage sensing for battery and BUS terminals, accurate rail-rail current sensing for battery current, BUS current and up-to 4 USB ports currents. PL62006 can work with a general MCU to provide a complete, powerful and flexible buck-boost charging system for all kinds of fast charge application such as power bank, battery packs, or portable energy cubic etc.

In charging mode, it steps up or down the input voltage to effectively charge the batteries. PL62006 supports trickle charging, constant current (CC) charging and constant voltage (CV) charging management. The charging current and charging voltage can be programmed by two 12-bit DAC converters.

The PL62006 features I²C interface, so the user can easily control the charging/discharging mode, and program charging current, charging voltage, output voltage, and output current limits through I²C. It also monitors the status of up to four USB ports and provides four NMOS gate drivers to control the power path independently. User can also use I²C to monitor the status of DC-DC, even the whole system.

PL62006 also provides VMONP pin, through which the MCU can monitor VBUS, VBAT voltage, IBUS, IBAT current and the current of each port in real time. All these features simplify the system design and reduce BOM cost for any charging system.

The PL62006 supports under voltage protection, over voltage protection, over current protection, short circuit protection and over temperature protections to ensure system safety under different abnormal conditions.





Fig. 4-1 Typical Application Schematic





Fig. 5-1 Top view



Pin		Description		
Number	Name	Description		
0	GND	Exposed pad of the package, Ground connection for internal circuits		
1	CSNBUS	Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor.		
2	2 CSPBUS Positive input of a current sense amplifier. Connect to one terminal of the curren sense resistor.			
3	VGC	NMOS gate driver to control the external NMOS of C1 port		
4	VC	Used to sense the voltage of C port.		
5	VGB	NMOS gate driver to control the external NMOS of B port		
6	VB	Used to sense the voltage of B port.		
7	VGC2	NMOS gate driver to control the external NMOS of C2 port		
8	VC2	Used to sense the voltage of C2 port.		
9	VGA1	NMOS gate driver to control the external NMOS of A1 port		
10	VA1	Used to sense the voltage of A1 port.		



12 SCLP I ² C clock line. Connect with a pull up resistor (typical 10kΩ). Connect to MCU 13 SDAP I ² C data line. Connect with a pull up resistor (typical 10kΩ). Connect to MCU 14 INTP Open drain output for interrupt signal. Connect to MCU 15 RXOVER Multi-function pin to connect with MCU [00:RXOVER 01: VRDAC2P05 10: CLK1MS 11:IFB_B] 16 RXCR Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 17 IREF Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 0 Output of internal SV linear regulator. 20 VDD Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2/ FB2/ 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections <th>11</th> <th>VMONP</th> <th colspan="3">Used to detect VBUS/VBAT voltage, IBUS/IBAT current, and the voltage drop of cut-off MOS for A/B/C1/C2 ports. Connect this pin to MCU</th>	11	VMONP	Used to detect VBUS/VBAT voltage, IBUS/IBAT current, and the voltage drop of cut-off MOS for A/B/C1/C2 ports. Connect this pin to MCU		
14 INTP Open drain output for interrupt signal. Connect to MCU 15 RXOVER Multi-function pin to connect with MCU [00:RXOVER 01: VRDAC2P05 10: CLK1MS 16 RXCR Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 17 IREF Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal SV linear regulator. 20 VDD Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN 22 VINALL Power supply to the IC. Connect to power rails with low voltage schottky diodes. 23 VREF Reference voltage for voltage control loop 24 FB21 Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. <tr< td=""><td>12</td><td>SCLP</td><td></td></tr<>	12	SCLP			
15 RXOVER Multi-function pin to connect with MCU [00:RXOVER 01: VRDAC2P05 10: CLK1MS 11:IFB B] 16 RXCR Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 17 IREF Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal 5V linear regulator. Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB21 Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 31 HG1 High side gate driver of switch MOS	13	SDAP	I ² C data line. Connect with a pull up resistor (typical 10kΩ). Connect to MCU		
15 RXOVER Multi-function pin to connect with MCU [00:RXOVER 01: VRDAC2P05 10: CLK1MS 11:IFB_B] 16 RXCR Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 17 IREF Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT] 18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal 5V linear regulator. Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2I Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 31 HG1 High side gate driver of switch MOS	14	INTP	Open drain output for interrupt signal. Connect to MCU		
17 IREF Multi-function pin to connect with MCU [00:IREF 01: FB1 10: ADDSEL 11:IFB A1] 18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal SV linear regulator. Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2/ Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 31 HG1 High side gate driver of switch MOS 32 BST1 Book-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 33 SW1 Power switching pin. Connect this pin to the switching node of inductor.	15	RXOVER	Multi-function pin to connect with MCU [00:RXOVER 01: VRDAC2P05 10: CLK1MS		
18 VP1P2 1.2V power supply. 19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal 5V linear regulator. Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB21 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Place a 1µF capacitor from this pin to GND as close to the IC as possible. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 35 VCC	16	RXCR	Multi-function pin to connect with MCU [00:RXCRC 01: 0.9V 10: CLK_DIGT]		
19 MCULDO 3.3V voltage output for MCU 20 VDD Output of internal 5V linear regulator. Connect a 1μF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1μF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2/ Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37	17	IREF	Multi-function pin to connect with MCU [00:IREF 01: FB1 10: ADDSEL 11:IFB_A1]		
20 VDD Output of internal 5V linear regulator. Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB21 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35	18	VP1P2	1.2V power supply.		
20 VDD Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible. 21 EN Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 <i>FB21</i> 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 <i>NC</i> This pin is floating, do not have electrical connections 27 <i>NC</i> This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Place a 1µF capacitor from this pin to GND as close to the IC as possible. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS<	19	MCULDO			
Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible.21EN22VINALLPower supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible.23VREFReference voltage for voltage control loop24FB2/25COMPError amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin.26NCThis pin is floating, do not have electrical connections27NCThis pin is floating, do not have electrical connections28CSN1Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.29CSP1Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.30VBATBattery voltage or Input voltage.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect to 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower switching pin. Connect this pin to the switching node of inductor.38BST2the high side gate driver of switch MOS39HG2High side gate driver of switch MOS			Output of internal 5V linear regulator.		
21 EN 22 VINALL Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB21 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 11 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power Switching pin. Connect this pin to the switch	20	VDD	Connect a 1µF capacitor from VDD pin to GND as close to the IC as possible.		
22 VINALL Power supply to the IC. Connect to power rails with low voltage schottky diodes. Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2/ 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 33 SW1 Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35<	21	FN			
22 VINALL Place a 1µF capacitor from this pin to GND as close to the IC as possible. 23 VREF Reference voltage for voltage control loop 24 FB2/ 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 9 CSP1 Battery voltage or Input voltage. 9 NBAT Place a 1µF capacitor from this pin to GND as close to the IC as possible. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect to Switch MOS 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for hi			Power supply to the IC. Connect to power rails with low voltage schottky diodes.		
23 VREF Reference voltage for voltage control loop 24 FB2/ 25 COMP Error amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 91 CSP1 Battery voltage or Input voltage. 92 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 32 BST1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 <td>22</td> <td>VINALL</td> <td></td>	22	VINALL			
24FB2/25COMPError amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin.26NCThis pin is floating, do not have electrical connections27NCThis pin is floating, do not have electrical connections28CSN1Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.29CSP1Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.30VBATBattery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS35VCCPower Switching pin. Connect this pin to the switching node of inductor.36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS39HG2High side gate driver of switch MOS					
25COMPError amplifier output and input to the PWM comparator. Connect frequency compensation components to this pin.26NCThis pin is floating, do not have electrical connections27NCThis pin is floating, do not have electrical connections28CSN1Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.29CSP1Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.30VBATBattery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS39HG2High side gate driver of switch MOS			Reference voltage for voltage control loop		
23 COMP compensation components to this pin. 26 NC This pin is floating, do not have electrical connections 27 NC This pin is floating, do not have electrical connections 28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38	24	FB2I			
27NCThis pin is floating, do not have electrical connections28CSN1Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.29CSP1Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.30VBATBattery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS		COMP	compensation components to this pin.		
28 CSN1 Negative input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 29 CSP1 Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side. 30 VBAT Battery voltage or Input voltage. 31 HG1 High side gate driver of switch MOS 32 BST1 Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver. 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2					
28CSN1sense resistor in the VBAT side.29CSP1Positive input of a current sense amplifier. Connect to one terminal of the current sense resistor in the VBAT side.30VBATBattery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver of switch MOS39HG2High side gate driver.	27	NC			
29CSP1sense resistor in the VBAT side.30VBATBattery voltage or Input voltage. Place a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS	28	CSN1			
30VBATPlace a 1µF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS	29	CSP1			
Place a 1μF capacitor from this pin to GND as close to the IC as possible.31HG1High side gate driver of switch MOS32BST1Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1μF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS	30	VBAT	Battery voltage or Input voltage.		
32BST1Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.33SW1Power Switching pin. Connect this pin to the switching node of inductor.34LG1Low side gate driver of switch MOS35VCCPower supply for high side and low side driver36LG2Low side gate driver of switch MOS37SW2Power Switching pin. Connect this pin to the switching node of inductor.38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS		VB/(T	Place a $1\mu F$ capacitor from this pin to GND as close to the IC as possible.		
32 BST1 the high side gate driver. 33 SW1 Power Switching pin. Connect this pin to the switching node of inductor. 34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2 High side gate driver of switch MOS	31	HG1	High side gate driver of switch MOS		
34 LG1 Low side gate driver of switch MOS 35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2 High side gate driver of switch MOS	32	BST1			
35 VCC Power supply for high side and low side driver 36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2 High side gate driver of switch MOS	33	SW1	Power Switching pin. Connect this pin to the switching node of inductor.		
36 LG2 Low side gate driver of switch MOS 37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2 High side gate driver of switch MOS	34	LG1			
37 SW2 Power Switching pin. Connect this pin to the switching node of inductor. 38 BST2 Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver. 39 HG2 High side gate driver of switch MOS	35	VCC	Power supply for high side and low side driver		
38BST2Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power the high side gate driver.39HG2High side gate driver of switch MOS	36	LG2	Low side gate driver of switch MOS		
38 BS12 the high side gate driver. 39 HG2 High side gate driver of switch MOS	37	SW2			
39 HG2 High side gate driver of switch MOS	38	BST2	Boot-Strap pin Connect a 0.1µF or greater capacitor between SW and BST to power		
	39	HG2			
		VBUS	Power node of the charger.		

6 Device Marking Information

Part Number	Order Information	Package	Package Qty	Top Marking
PL62006	PL62006IQN40A	QFN5X5-40	2500	62006 RAAYMD

PL62006: Part Number RAAYMD: RAA: LOT NO.; YMD: Package Date



7 Specifications

7.1 Absolute Maximum Ratings^(Note1) Over operating free-air temperature range (unless otherwise noted).

		MIN	МАХ	Unit
	VC, VBUS, VBAT, VINALL, CSP1, CSN1, CSPBUS, CSNBUS, SW1, SW2	-0.3	40	
	VA1, VB, VC2	-0.3	30	
	VGA1-VA1, VGB-VB, VGC-VC, VGC2-VC2,	-0.3	15	
Voltage range at	VGA1-VBUS, VGB-VBUS, VGC-VBUS, VGC2-VBUS	-0.3	15	
terminals (Note2)	BST1 to SW1, BST2 to SW2	-0.3	7	V
	HG1 to SW1, HG2 to SW2	-0.3	7	
	COMPI, VMONP, SCLP, SDAP, INTP, RXOVER, RXCR, IREF, VP1P2, MCULDO, VDD, VREF, LG1, LG2, FB2I	-0.3	6.5	
	Others	-0.3	6.5	

Tab. 7-1-1 Absolute Maximum Ratings

7.2 Handling Ratings

Tab. 7-2-1 Handling Ratings

PARAMETER	DEFINITION	MIN	MAX	UNIT
T _{ST}	Storage Temperature Range	-65	150	°C
TJ	Junction Temperature		+160	°C
TL	Lead Temperature		+260	°C
	HBM Human body model	2	4	kV
VESD	CDM Charger device model		500	V

7.3 Recommended Operating Conditions (Note 3)

Tab. 7-3-1 Recommended Operating Conditions

		MIN	МАХ	Unit
	VA, VB, VC, VBUS, VBAT, VPWR, CSP1, CSN1, CSPBUS, CSNBUS, SW1, SW2, VINALL	-0.3	32	
	VA1, VB, VC2	-0.3	28	
	VGA1-VA1, VGB-VB, VGC-VC, VGC2-VC2,	-0.3	12	
Voltage range at	VGA1-VBUS, VGB- VBUS, VGC- VBUS, VGC2- VBUS	-0.3	12	
terminals ^(Note2)	BST1 to SW1, BST2 to SW2	-0.3	6.5	V
	HG1 to SW1, HG2 to SW2	-0.3	6.5	
	COMPI, VMONP, SCLP, SDAP, INTP, RXOVER, RXCR, IREF, VP1P2, MCULDO, VDD, VREF, LG1, LG2, FB2I	-0.3	6.5	
	Others	-0.3	6.5	



UNIT

V

V

V V

mV V

mV V

μΑ

μΑ

mΑ

mΑ

V

mΑ

V

V

V

V

kHz

kHz

kHz

kHz

V

V

V

7

150

300

1

8000

4.2

2*4.2

3*4.2

Tab. 7-4-1 Thermal Information

Symbol Description		QFN5X5-40	Unit
θ」Α	Junction to ambient thermal resistance	43	°C/W
θյς	Junction to case thermal resistance	8	C/VV

Notes:

Vcp

 F_{SW}

 $F_{\text{CLK}_1\text{ms}}$

F_{CLK_Dig}

 $V_{\text{BAT_chg}}$

Oscillators

drivers

Charge pump voltage

Switching frequency

CLK for digital core

Battery full-charge voltage

1ms CLK for CC scan and timer

1) Exceeding these ratings may damage the device.

2) All voltage values are with respect to network ground terminal.

3) The device function is not guaranteed outside of the recommended operating conditions.

4) Measured on approximately 1" square of 1 oz copper.

7.5 Electrical Characteristics

(Typical at VBUS = 12V, VBAT = 3.6V, T_J=25°C, unless otherwise noted.)

SYMBOL	PARAMETER	CONDITION	MIN	TYP	MAX	Τ
Power supp	, blies	•				
VBUS	Input voltage on VBUS		3.5		32	Γ
VBAT	Input voltage on VBAT		3.2		32	Γ
VINALL	Input voltage on VINALL		3.2		32	Γ
V _{UVLO_VBUS}	VBUS under-voltage lockout	Charging mode, rising edge		3.5		
V UVLO_VBUS	threshold	Hysteresis		180		L
Vuvlo_vbat	VBAT under-voltage lockout	Discharging mode, Rising edge		3.2	3.3	
	lineshold	Hysteresis		220		
V_{UVLO_VINALL}	VINALL under-voltage lockout threshold			1.2		
I _{Q_shutdown}	shutdown current	VBAT= 8.4V, EN = 0		0	1	
I _{Q_stdby}	Standby current	VBAT= 8.4V, GOACTIVE = 0		60	80	
I _{Q_noclk}	Quiescent current with digital CLK disabled	VBAT= 8.4V, GOACTIVE = high, DISCLK = high, ENDCDC=low		2		
I _{Q_nodcdc}	Quiescent current with DC-DC disabled	VBAT= 8.4V, GOACTIVE = high, DISCLK = low, ENDCDC=low		12		
V _{DD}	VDD regulation voltage	VINALL = 12V, I _{VDD} = 1~70mA	4.9	5.1	5.35	
I _{VDD_LIM}	VDD regulator current limit	VINALL = 12V, VDD = 4V	40	80	120	Γ
V _{MCULDO}	LDO regulation voltage	LDO set to 3.3V, ILDO = 1~50mA	3.23	3.30	3.37	
V _{VP1P2}	1.2V power supply for BMC voltage	VINALL = 12V, connect 1uF from VP1P2 pin to GND.		1.2		
V _{VCC}	Power supply for buck-boost	VBAT = 12V, connect 1uF		6.6		Γ

Tab. 7-5-1 Electrical Characteristics

Battery Charging

1 cell

2 cell

3 cell

from VCC pin to GND.

FSW_SET = 00

FSW_SET = 01

VBAT = 8.4V, VBUS=0V



PL62006

						LOZU
		4 cell		4*4.2		V
		5 cell		5*4.2		V
		6 cell		6*4.2		V
		1 cell		3.5		V
		2 cell		2*3.5		V
VDAT	Battery full-charge voltage for 3.5V	3 cell		3*3.5		V
VBAT_chg3p5	battery cell	4 cell		4*3.5		V
		5 cell		5*3.5		V
		6 cell		6*3.5		V
		VREG_SET = 00,	4.4	4.5	4.6	V
VINREG	VINREG voltage regulation	VREG_SET = 01	8	8.1	8.2	V
• INICES		VREG_SET = 10	10.7	10.8	10.9	V
		VREG_SET =11	17.9	18	18.1	V
V _{EOC}	End of charge voltage threshold		98%	99%	100 %	
V _{RECHG}	Recharge threshold		96.0 %	97.6%	98.8 %	
V _{CHG_OV}	Battery over charge voltage			105%		
Dischargin	· · · · ·					
VVREF	Reference voltage for voltage loop			2.0		V
VIREF	Reference voltage for current loop			2.0		V
Isink_compi	COMPI sink current	VFB=VREF+100mV		15		uA
ISOUR_COMPI	COMPI source current	VFB=VREF-100mV		20		uA
Port detect						
Vc1_rdy	Plug-in detection threshold for port C1 used as charging port		4.3	4.4	4.5	V
V _{B_RDY}	Plug-in detection threshold for port B used as charging port		4.3	4.4	4.5	V
V _{C2_RDY}	Plug-in detection threshold for port C2 used as charging port		4.3	4.4	4.5	V
VA1_DET	Plug-in detection threshold for port A1 used as discharging port		1.9	2	2.1	V
Vb_det	Plug-in detection threshold for port B used as discharging port		1.9	2	2.1	V
I _{COM}	Small current detection threshold for I _{BUS}	Falling edge	10	50	80	mV
Cut-off swi	itch control	•				
ITURNONC	C1 port cut-off switch turn on current			1		uA
I _{TURNONB}	B port cut-off switch turn on current			1		uA
ITURNONA1	A1 port cut-off switch turn on current			1		uA
Iturnonc2	C2 port cut-off switch turn on current			1		uA
l²C						
VIL	SCLP, SDAP input low voltage				0.4	V
V _{IH}	SCLP, SDAP input high voltage		1.2			V
THERMAL	SHUTDOWN		•			•
		Rising		165		°C
T _{SD}	Thermal shutdown temperature	Hysteresis		15		°C
		11931010313		15		

Note:

1) Guaranteed by design



8 Detailed Description

8.1 Overview

PL62006 is a high efficiency, synchronous bi-directional buck-boost charger It is a comprehensive and flexible buck-boost charger platform designed for most of fast charging application with type-C port and PD protocol. It can be programmed to buck charging, boost charging or buck-boost charging. PL62006 provides I2C interface to communicate with MCU, provides high voltage sensing for battery and BUS terminals, accurate rail-rail current sensing for battery current, BUS current and up-to 4 USB ports current.PL62006 can work with a general MCU to provide a complete, powerful and flexible buck-boost charging system for all kinds of fast charge application such as power bank, battery packs, or portable energy cubic etc.

8.2 Functional Block Diagram



Fig. 8-2-1 PL62006 Diagram



Two registers are used for charge setting: CHG_CTR1 (0X04H) and CHG_CTR2 (0X05H). In order to charge a battery, the following setting are needed to be set up correctly:

- 1. Use BAT_CELL<2:0> to set up the number of cells in series for battery pack
- 2. It is optional to use register 0X2EH register to adjust the full battery voltage
- 3. Set register 0X1BH for a correct adaptive charging VREG point
- 4. Set bits 0X20H<7:6> to 11 to set IBUS sense gain to 200
- 5. Set bit 0X2DH<4> high to enable BUS constant current (CC) loop
- 6. Set correct value for 0X08H register to set up a needed charge current value. When battery voltage is low, set a small value for 0X08H register for trickle charge stage.
- 7. Set correct value in 0X1CH to turn on the cut-off switch for the corresponding charge port
- 8. Make sure that the value of battery type bit BATTYPE 0X04H<7> is correct
- 9. Make sure that OTG bit is 0 for battery charging

After all of the registers are set up correctly, set EN_DCDC bit high to turn on DC-DC and start up to charge battery. During charging, MCU can keep monitoring the status of the whole system by checking status registers and VMONP signal.

The default value of FDCM bit is high, which will force DC-DC to work in forced DCM mode. It is a good choice to start up the system for battery charging in forced DCM mode and set IBUS current limit to a low value. Once the battery voltage ramps above the trickle charge threshold, slowly ramp up IBUS current limit to a higher value (a good choice for IBUS current is 0.5A), then set FDCM bit low to allow the system to work in CCM mode. Sometimes, it may be helpful to make the system transit smoothly from DCM mode to CCM mode by setting VDCMSET<1:0> to 00 to lower down DCM-CCM transition point.

When the battery voltage is very close to full-charge voltage point, it will be better to lower down IREF value slowly by setting 0X08H at lower value. When the inductor current is lower down to be close to be around 0.3A, it is better to set FDCM bit high to force the system working in DCM mode again. When the cell voltage reaches the VBAT target, it enters into Constant Voltage charge phase, and charges the cells with gradually decreased current. Once termination voltage and termination current conditions are satisfied, the IC enters into End of Charge phase if ENEOC bit is high. In this phase the IC will terminate the charging.

User can set ENEOC bit to 0, system will not turn off DC-DC and charge the battery to the setting point. MCU can check battery voltage to determine when to terminate the charge. This mode is especially suitable for small current battery charging such as TWS.

After the battery is fully charged, it is better to disable DC-DC by setting ENDCDC bit low. Sometimes, it may be helpful to set 0X2EH<7> high to force the system go into standby mode to lower down quiescent current to be around 60uA.

If the IC terminates charging after EOC, the battery voltage may drop due to leakage or operation current from battery cells. Once the VBAT voltage drops below VRECH threshold, the IC enters into CC charge phase to recharge the battery. User can also use MCU to monitor battery voltage. Once the battery voltage reaches recharge threshold, MCU can enable the charge again.

During charging, if the IBUS charging current is higher than adapter's current capability, the adapter will be overloaded and VBUS voltage will be pulled lower. PL62006 supports dynamic power management; the allowed minimum VBUS operation voltage for charging is set by VINREG_SET [2:0]. Once VBUS voltage drops to V_{INREG} threshold, the IC reduces the charging current automatically and regulates the VBUS at V_{INREG} threshold. If the VBUS voltage drops below VINREG threshold, the IC reduces the charging current to 0.

8.4 Discharging Mode

When OTG bit is set to1, the IC is set to discharging mode. If FB_SEL is set to 0, internal feedback resistors are used, and the VBUS output is set by 0X06H and 0X07H registers. The default VBUS output voltage is 5V, and can be adjusted from 0V to 20V with 0.5mV per step as below:

VBUS (V) =2.15mV×(VBUS_SET[11]×2¹¹ + VBUS_SET[10]×2¹⁰+.....VBUS_SET[0]×2⁰)

User shall write LDVREF bit to 1 to load the VBUS setting, otherwise the change will not take effect. If constant current loop is needed, user need to set bit 0X2DH<4> high to enable BUS constant current (CC) loop.

8.4.1 PFM Operation

To reduce the switching loss, the IC features Pulse-Frequency Modulation (PFM) operation under light load condition for discharging mode. The IC decreases the frequency automatically to reduce the switching loss so the efficiency can be improved under light load condition. User can also set 0X00H<3> to 1 to force the system to working in CCM mode. FDCM



bit has higher priority than MODE bit, which means that system will work in DCM mode even if MODE is high with FDCM = 1.

8.4.2 Current Limit in Discharging Mode

When OTG is set to 1, the IC monitors the discharging current through the voltage drop from CSNBUS pin to CSPBUS pin (opposite direction of charging mode). User need to set bit 0X2DH<4> high to enable BUS constant current (CC) loop.

8.5 Port control

PL62006 integrates the port detection and control circuit for up to four USB ports: C1, C2, A and B.

For USB-A port, it can only work as discharging port, and only current from VBUS to VA is allowed. It supports phone insert detection function.

For B port, it can be configured as either charging port or discharging port.

- 1. If BMODE =1, it works as charging port: adapter insert and removal detection are supported, and the current shall flow from VB to VBUS.
- 2. If BMODE = 0, it works as discharging port: phone insert detection function is supported, and the current shall flow from VBUS to VB.

For C port, it is normally used for DRP TYPE-C port depending CCMOD<1:0> bits setting in 0X28H register.

8.6 Power Path Management

The IC provides four NMOS gate drivers for A/B/C1/C2 ports respectively.

The NGATE driver must be combined with corresponding port, that is, VGA1 can only be used for VA1 can only be used for VGC1 can only be used for VC1, VGC2 only for VC2, and VGB only for VB.

Either a single NMOS or back-to-back NMOS can be used for each port as shown in typical application circuit. The VGS rating of the NMOS must be considered for the safe operation.

The NGATE driver is controlled by register 0X1CH.

For each port, a full protection system is designed such as over voltage, over current and short-circuits protection.

8.7 Phone Insert Detection

For the discharging port (VA1 or VB with BMODE = 0), phone insert detection function is supported.

While the isolation MOS is off, the port is only biased by an internal weak pull up. After a phone is inserted, the port voltage is pulled low by the operating current of the phone, so the IC can detect the phone attachment. When phone insert is detected, the corresponding interrupt bit (APLOW or BPLOW) is set to inform MCU.

8.8 Adapter Detection

For the charging port (VB with BMODE =1, VC , VC2), the IC can detect the attachment / detachment of the adapter, and indicate the status through VBRDY, VC1RDY, VC2RDY bits in register 0X36H.

8.9 Small Current Indication

The IC monitors its output port current in discharging mode. Once the port current is lower than 50mA typically, it reports the status to MCU through INT bit.

8.10 Current and Voltage Monitor Function

A specific pin VMONP is used to monitor the system currents and voltages. To turn on VMONP function, set bit 0X1CH<2> high and use register bits 0X2DH<3:0> to select different signals to be sent to VMONP pin. MCU can use ADC to monitor the system status.

8.11 Operation Modes

There are totally 4 operation modes in PL62006: shutdown mode, standby mode, no digital clock mode, no DC-DC mode and normal mode.

1. Shutdown mode: when EN_DCDC bit low, the whole system will be off and Iq will be close to be 0 uA.



- Standby mode: if no equipment is attached to PL62006 or 0X2EH<7> is set high, GOACTIVE bit will be low and PL62006 will be in standby mode. I_q will be around 60uA in this mode. Only port detection circuit and MCU LDO are alive in this mode.
- No digital clock mode: if GOACTIVE is high and DISCLK in register 0X27H is set high, the digital clock will be disabled. All of the power supplies such as VDD, VCC, MCULDO etc. are all alive in this mode. Digital core will be disabled in this mode.
- 4. No DC-DC mode: if GOACTIVE is high and DISCLK is low, ENDCDC=low, all other circuits are all alive except that DC-DC is disabled.
- 5. Normal mode: if GOACTIVE is high, DISCLK is low and ENDCDC is high, PL62006 enters normal mode for charging or discharging.



9 Application and Implementation

9.1 Inductor Selection

The operating frequency and inductor selection are interrelated in that higher operating frequencies allow the use of smaller inductor and capacitor values. The inductor value has a direct effect on ripple current. The inductor current ripple ΔI_L is typically set to 20% to 40% of the maximum inductor current in the boost region at V_{IN(MIN)}.

For a given ripple the inductance terms in continuous mode are as follows:

$$L_{BOOST} > \frac{V_{IN(MIN)}^{2*}(V_{OUT}-V_{IN(MIN)})^{*1000}}{f^{*1}_{out_{max}}^{*40\%*}V_{OUT}^{2}} H$$

$$L_{BUCK} > \frac{V_{OUT}^{*}(V_{IN(MAX)}-V_{OUT})^{*100}}{f^{*}\Delta I_{L}^{*}V_{IN(MAX)}} H$$

where: f is operating frequency, kHz

 $V_{IN(MIN)}$ is minimum input voltage, V

 $V_{IN(MAX)}$ is maximum input voltage, V

VOUT is output voltage, V

△IL is maximum inductor ripple current, A, usually select 20~40% maximum output current.

For high efficiency, choose an inductor with low core loss, such as ferrite. Also, the inductor should have low DC resistance to reduce the I²*R losses, and must be able to handle the peak inductor current without saturating. To minimize radiated noise, use a toroid, pot core or shielded bobbin inductor.

9.2 C_{IN} and C_{OUT} Selection

In boost region, input current is continuous. In buck region, input current is discontinuous. In buck region, the selection of input capacitor C_{IN} is driven by the need to filter the input square wave current. Use a low ESR capacitor sized to handle the maximum RMS current. For buck operation, the input RMS current is given by:

$$I_{\text{CIN}} = I_{\text{OUT}(\text{MAX})} \times \sqrt{\frac{V_{\text{OUT}}}{V_{\text{IN}}} \times \left(1 - \frac{V_{\text{OUT}}}{V_{\text{IN}}}\right)}$$

This input current has a maximum at $V_{IN} = 2V_{OUT}$, $I_{CIN(MAX)} = I_{OUT(MAX)}/2$.

In the boost region, C_{OUT} must be capable of reducing the output voltage ripple because of the discontinuous output current. The effects of ESR (equivalent series resistance) and the bulk capacitance must be considered when choosing the right capacitor for a given output ripple voltage. The steady ripple due to charging and discharging the bulk capacitance is given by:

$$\Delta V_{(BOOST,Cap)} = \frac{I_{OUT(MAX)}^{*} (V_{OUT} - V_{IN(MIN)})}{C_{OUT}^{*} V_{OUT}^{*} f} V$$

Where C_{OUT} is the output filter capacitor.

The steady ripple due to the voltage drop across the ESR is given by:

 $\Delta V_{(BOOST,ESR)} = I_{OUT(MAX,BOOST)} * ESR$

In buck mode, V_{OUT} ripple is given by:

$$\Delta V_{OUT} \leq \Delta I_{L}^{*} \left(ESR + \frac{1}{8^{*} f^{*} C_{OUT}} \right)$$

Multiple capacitors placed in parallel may be needed to meet the ESR and RMS current handling requirements.

9.3 Power MOSFETs Selection and Efficiency Considerations

PL62006 requires four external N-channel power MOSFETs, two for the top switches (switches Q1 and Q4, shown in Figure 1) and two for the bottom switches (switches Q2 and Q3, shown in Figure 1). Important parameters for the power MOSFETs are the breakdown voltage $V_{BR, DSS}$, threshold voltage $V_{GS,TH}$, on-resistance $R_{DS(ON)}$, reverse transfer capacitance C_{RSS} and maximum current $I_{DS(MAX)}$. The drive voltage is set by the VCC supply.



PL62006

In order to select the power MOSFETs, the power dissipated by the device must be known. For switch Q1, the maximum power dissipation happens in the boost region, when it remains on all the time. Its maximum power dissipation at maximum output current is given by:

$$\mathsf{P}_{Q1,BOOST} = \left(\frac{\mathsf{V}_{OUT}}{\mathsf{V}_{IN}} * \mathsf{I}_{OUT(MAX)}\right)^2 * k^* \mathsf{R}_{\mathsf{DS}(ON)}$$

Where *k* is a normalization factor (unity at 25°C) accounting for the significant variation in on-resistance with temperature. For a maximum junction temperature of 125°C, using a value k = 1.5 to show temperature influence on resistance. R_{DS(ON)} is the normalized value at 25°C.

Switch Q2 operates in the buck region as the synchronous rectifier. Its power dissipation at maximum output current is given by:

$$\mathsf{P}_{\mathsf{Q2,BUCK}} = \frac{\mathsf{V}_{\mathsf{IN}} \cdot \mathsf{V}_{\mathsf{OUT}}}{\mathsf{V}_{\mathsf{IN}}} * \mathsf{I}_{\mathsf{OUT}(\mathsf{MAX})}^{2} * \mathbf{k}^* \mathsf{R}_{\mathsf{DS}(\mathsf{ON})}$$

Switch Q3 operates in the boost region as the control switch. Its power dissipation at maximum current is given by:

$$P_{Q3,BOOST} = \frac{(V_{OUT} - V_{IN})^* V_{OUT}}{V_{IN}^2} * I_{OUT(MAX)}^2 * k^* R_{DS(ON)} + r^* V_{OUT}^3 * \frac{I_{OUT(MAX)}}{V_{IN}} * C_{RSS} * f$$

Where C_{RSS} is usually specified by the MOSFET manufacturers. The constant *r*, which accounts for the loss caused by reverse recovery current, is inversely proportional to the gate drive current and has an empirical value of 1.7.

For switch Q4, the maximum power dissipation happens in the boost region, when its duty cycle is higher than 50%. Its maximum power dissipation at maximum output current is given by:

$$\mathsf{P}_{\mathsf{Q4},\mathsf{BOOST}} = \frac{\mathsf{V}_\mathsf{IN}}{\mathsf{V}_\mathsf{OUT}} * \left(\frac{\mathsf{V}_\mathsf{OUT}}{\mathsf{V}_\mathsf{IN}} * \mathsf{I}_\mathsf{OUT(MAX)}\right)^2 * \textit{k}^* \mathsf{R}_\mathsf{DS(ON)}$$

For the same output voltage and current, switch Q1 has the highest power dissipation and switch Q2 has the lowest power dissipation unless a short occurs at the output. From a known power dissipated in the power MOSFET, its junction temperature can be obtained using the following formula:

$$T_j = T_a + P^* \theta_{TH(JA)}$$

The $\theta_{TH(JA)}$ to be used in the equation normally includes the $\theta_{TH(JC)}$ for the device plus the thermal resistance from the case to the ambient temperature ($\theta_{TH(JC)}$). This value of T_j can then be compared to the original, assumed value used in the iterative calculation process. Based on the T_j requirement for a given MOSFET and regulator efficiency requirement, we can choose suitable part.

9.4 Output voltage setting

PL62006 VBUS voltage is set by an external feedback resistive divider carefully placed across the output capacitor. 1% accuracy resistor is preferred for this divider. The resultant feedback signal is compared with the internal precision VREF voltage reference by the error amplifier. The output voltage is given by the equation:

$$V_{BUS} = VREF * \left(1 + \frac{R_1}{R_2}\right)$$



where R_1 is the upper resistor and R_2 is the lower resistor in the feedback network.

9.5 Current Sense Resistor

A power resistor with $10m\Omega$ or less should be used to sense IBUS current and IBAT current. Resistor of 1% or higher accuracy and low temperature coefficient is recommended.



The resistor power rating and temperature coefficient should be considered. The power dissipation can be roughly calculated as $P=I^{2*}R$, and I is the RMS current flowing through the resistor. The resistor power rating should be higher than the calculated value.

Normally the resistor value is varied if the temperature increased and the variation is decided by temperature coefficient. If high accuracy of current limit is required, select lower temperature coefficient resistor.

9.6 Isolation MOSFET Selection

For each port, N-channel MOSFET can be used as isolation switch. When selecting the MOSFET, user shall consider the VGS rating, VDS rating and R_{dson} parameters. When the gate driver is turned on, the IC outputs high voltage based on the lower voltage of VBUS and port voltage. A clamping circuit is designed to guarantee that the VGS voltage will not exceed 8V.

9.7 Diode Selection

PL62006 use VINALL pin to power the internal driver circuits and the LDOs; if a back-to-back isolation is used on a charging port, the port voltage shall also be connected to VINALL pin through a schottky diode. Schottky diodes with small voltage drop such as SS14L are recommended for applications with low battery voltage.



10 PCB Layout

Layout is a critical portion of good power supply design. The following guidelines will help users design a PCB with the best power conversion performance, thermal performance, and minimized generation of unwanted EMI.

- 1. The input bypass capacitor must be placed as close as possible to the VBUS pin and ground pin to decouple input noise.
- 2. The output bypass capacitor must be placed as close as possible to the VBAT pin and ground to decouple output noise.
- 3. Grounding for both the input and output capacitors should consist of localized top side planes that connect to the GND pin and PAD.
- 4. The inductor L should be placed close to the SW pin to reduce magnetic and electrostatic noise.
- 5. CSP1, CSN1, CSPBUS, CSNBUS should directly connected to sensing resistor terminals, and symmetrically route to IC with a kelvin connection style.
- 6. It is better to separate inductor, power MOSFETs, input bulk capacitor, output bulk capacitor to make a good thermal balance.
- 7. Put IC away from inductor, power MOSFETs. It is better to use a ground plane



11 Packaging Information



Currents el	Dimension in Millimeters				
Symbol	MIN	NOM	MAX		
A	0.8	0.85	0.9		
A1	0	0.02	0.05		
A2		0.65			
A3		0.203 REF			
b	0.15	0.2	0.25		
D		5 BSC			
E		5 BSC			
е		0.4 BSC			
D2	3.3	3.4	3.5		
E2	3.3	3.4	3.5		
L	0.3 0.4 0.5				
К	0.4 REF				

IMPORTANT NOTICE

Powlicon Microelectronics Co., Ltd. assumes no responsibility for any error which may appear in this document. Powlicon Microelectronics Co., Ltd. reserves the right to change devices or specifications detailed herein at any time without notice. Powlicon Microelectronics Co., Ltd. does not assume any liability arising out of the application or use of any product described herein; neither it convey any license under its patent rights, nor the rights of others. Powlicon Microelectronics Co., Ltd. products are not authorized for use as critical components in life support devices or systems without written approval letter from the Chief Executive Officer of Powlicon Microelectronics Co., Ltd. The user of products in such applications shall assume all risks of such use and will agree to not hold against Powlicon Microelectronics Co., Ltd. for any damage.